## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.








FIG. 1





FIG. 2





3/5


FIG. 4B -SUBSYNCHRONOUS DETECTION BOARD FOR 3 PHASE

Hz APPLICATIONS •%••%• **₽**2€ 2 D20 D19 **2 R25** 5 TB1 **TB2** TB8 INPUT PHASE 2

TB9 PHASE

 $\Box$ 

CT INPU **PHASE** 








FIG.